



OLENE S. WALKER
Governor
GAYLE F. McKEACHNIE
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

Supervisor

ORA

Inspection Report

Minerals Regulatory Program

Report Date: November 23, 2004

Mine Name: Bright 1 & 2

Operator or Permittee Name:

3-H Landscape Products LLC

Permittee Mailing Address:

2160 East Riverside Drive, St. George, Utah 84790

Inspector(s): Doug Jensen

Other Participants: Clint Gardner, 3-H Landscape

Permit Status: Active

Current Acreages: 19 Acres

Total Permitted (Bonded): 19 Acres

Total Disturbed: 19 Acres

Permit number: M/021/030

Inspection Date: November 15, 2004

Weather: Cool, Foggy

Inspection Start Time: 9:30 AM

Inspection End Time: 10:00 AM

Site location/Area Inspected (i.e. Pit #):
Quarries

Surface Ownership: BLM

Mineral Ownership: BLM

Mineral Mined:

Landscape Rock/ Rhyolite

Type of Mine: Quarries

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: November 15, 2004; Report Date November 23, 2004
Page 2 of 2
M/053/030

Purpose of Inspection:

Inspect the site while in the area.

Inspection Summary:

The site is clean and appears to be well run. The area was very wet, Clint indicated that mining had been shut down for a while due to rain in the area.

3-H is operating three quarries within this permit area. They have stockpiles located on the two northern quarry areas and processing equipment located at the center site.

Directions to the site:

The site is located ~2 miles west of Beryl junction off highway 56.

GPS data:

None gathered.

Inspector's Signature



Date: November 23, 2004

DJ:jb

cc: Clint Gardner, 3-H Landscape Products LLC
Ed Ginouves, BLM, Cedar City FO

O:\M021-Iron\M0210030-Bright1&2\Inspections\ins-11152004.doc